

Reference	SSM69998
Models	Range Rover (All New) / L405
Title	Vehicle judders during brake application
Category	Chassis
Last modified	07-Jan-2014 00:00:00
Symptom	301000 Service Brake System
Content	<p>Issue: During braking the customer reports the vehicle judders / shakes. This can occur at any speed but is most likely to be experienced when slowing from motorway speeds 70Mph (115Kmh) down to 50Mph (80Kmh).</p> <p>Cause: JLR engineering are aware of this concern and are currently investigating the root cause.</p> <p>Action: If the reported customer symptom is confirmed through testing then please raise an ePQR. JLR engineering will then make contact with further instructions / support.</p>