Jetta Bluetooth 000 051 743S manual coding procedure for

vehicles with PR code UF8- MDI.

Step 1) Install Bluetooth kit 000 051 473S

Step 2) Using VAS tester perform vehicle scan with ODIS.

Officeard Diagnostic Information System Service - 2.0.2									오 Offlowed Diagnostic Information System Service - 2.0.2						(10 K			
Importer:		444		VIN: SVA	VDX7AJ2DM433753				Importer:		444		VIN: SVM	/DX7AJ2DM433753		1		
Dealer:		03999		Engine: C81	TA 2.5 L Motronic / 125 KW	🥔 📩 🍗			Dealer:		03999		Engine: CBT	A 2.5 L Motronic / 125 KW	🥔 📩 🍗	6	YA.	
Order:		-							Order:		-						9	
Control modu	Operating modes *	^	Control mod	ilos Resu						Operating	modes	*						
Check composed int							Oe Discosis		-			S Chee	k component list			Ce Diano		
Control module list (49 entries)			The system has detected control modules				C and the		Control mod	Control module list (49 entries)		T	The system has detected control modules			C and the		
Address	Address Fault Name		that are not included in the specified equipment list.		🍘 Self Diagnosis		Address	Faus	Name	That are not included in the specified equipment list.				🍘 Sett D	lagnósis			
10		Parking Assistance	You can update the specified equipment list				Clash		10		Parking Assistano	You can update the specified equipment list						
20	0	High Beam Assist		Control to a data	Coding status	1			20	0	High Beam Assist		Control much for	Contra status				
		On a sind Examples of	22	Control module	Coding status	·	A Measurement		-		Consist Exection (Control module	Cooing status		A Moast	irement	
90		opecial Function a	- 11	Telephone	not coded		Defe		30		opecial Pullicitaria	01	Engine Control Module 1	ooded		Dinfo		
01	0	Engine Control Mc	01	Engine Control Module 1	coded	~			01	0	Engine Control Mo	02	Transmission Control Module	coded				
51		Drive Motor Contro	02	Transmission Control Module	coded	~	🚱 Admin		51		Drive Motor Contro	03	Brakes 1	coded	~	Admin 🚱		
								1										
61		Battery Regulation	03	Brakes 1	coded	·	Log ¥		61		Battery Regulation	04	Steering Angle Sender	coded	·	Log		¥
02	0	Transmission Cont	04	Steering Angle Sender	coded	 Image: A second s			02	0	Transmission Con	25	Immobilizer	coded	 Image: A set of the set of the			
22	0	All Wheel Control (25	Immobilizer	coded	~	Data *		22	0	Al Wheel Control	08	Air Conditioning	coded	~	Data		*
42	0	Door Electronics E					Extras ¥		42	0	Door Electronics D					Extras		¥
52		Door Electronics P	387			Close	Halo		62		Door Electronics P	38			Close	Halo		
62		Door Electronics R	-		The		62		Door Electronics P		Intriorser Denniedrit			Trop				
National disease Control and A link DTD assessment at the							Info ¥	e .	No. of the	Curt			Test Providence and Test			Info		×
Network diag	gram Cont	troi module list DTC m	amory I	ist Equipment list				-	Network dia	gram Cont	rol module list DIC n	iemory	list Equipment list					
Diagnosis 🕲 Display 🕸 Sorting							> 🛛 📀		Diagnosis Display N Sorting						3			
Disgnostic enforcement was stated.									Diagnosis enhancement was stated						-			

Step 3) The gateway installation list will come up and show the new telephone module is not coded. Change ADW 77 telephone to coded and select perform coding.



Step 4) Select network diagram, double cluck the

Red TEL 77 icon, select Control module OBD, Select

Code and press perform.

Importer: Dealer: Order:	444 03999 —		VIN: Engine:	3 C	WDX7AJ2DM433753 (8TA 2.5 L Motronic / 125 kW	an 🛃 🏷	
Control mo 77 - Telep System IC Byte no. 0 1 2 3 4 5 6	dules Results Orders https://docs/150TP177 TELEFON Current Nex value 0A 00 00 00 00 00 00 00 00 00	DISS TSB Test ; P6095730K / 3200 Current binary v 00001010 0000000 0000000 0000000 0000000 000000	In Operation	Special functions (NA / 002720) Current valu Hex 00 Binary 00000000 A	Code e Entry 10 00010000 ppty Cancel		Operating modes Degrosis Degrosis Self Degrosis Flash Comment Degrosis Info Degrosis Log Data
7 Check dig Apply OBD1 77	00 it 10 Restore Plain text o	0000000					Extras Help Online help Support

importer: Dealer:	444 03999	VI Er	N: ngine:	3VWDX7AJ2DM483763 CBTA 2.5 L Motronic / 125 KW 🥔 ң 🐄	
order: Control moi	dules Results Orders	DISS TSB Test plan	Operati	Special functions	Belf Diagnosis
7 - Teleol	tone (UDS/ISOTP/7	P6035730K / 3200 / H	15/EV 1	(VNA / 002720) Code 🖉 🔘	Riash
ystem ID	TELEFON	~			Measurement
Byte no.	Ourrent hex value	Ourrent binary value	e Hexin	ut Binary input	info 😭
0	04	00001010		Parlarm colleg? 🔤	Admin
	00	00000000	10	Do you really want to perform the coding?	
	00	00000000	04		Log ¥
3	00	00000000		Yes No	Data *
	00	00000000			Extras ¥
5	01	00000001			Hah e
Б	01	00000001			Online help
7	00	0000000			A Surged
Zheck digi	10				Sopport
Apply	Restore Plain text o	oding			info ¥

Step 5) Change function from adaption to code,

click on the Hex input box and enter new values.

Step 7) Clear faults, test operation and check for

any new DTC's have been stored.

.

Step 6) New coding should be 0A 10 04 00 00 01 01 00. Once the new values are entered select Yes to perform coding