

TECHNICAL BULLETIN  
LTB00319NAS3  
04 FEB 2014



© Jaguar Land Rover Limited  
All rights reserved.

**This reissue replaces all previous versions. Please destroy all previous versions. Only refer to the electronic version of this Technical Bulletin in TOPIx.**

Changes are highlighted in gray

**SECTION: 501-08**

Exterior A-Pillar Molding Loose

**AFFECTED VEHICLE RANGE:**

**LR4 (LA)**

**Model Year:** 2010-2012  
**VIN:** AA510742-CA680025

**LR3 (LA)**

**Model Year:** 2005-2009  
**VIN:** 5A000360-9A513325

**Range Rover Sport (LS)**

**Model Year:** 2005-2013  
**VIN:** 6A900290-DA778722

**MARKETS:**

NAS

**CONDITION SUMMARY:**

**Situation:** The exterior A-pillar molding may become loose.

**Cause:** This may be caused by the molding's retaining clips losing tension.

**Action:** Should a customer express this concern, follow the Service Instruction outlined below.

**PARTS:**

LR053837	A-Pillar Retaining Clips Fitting kit	Quantity: 1
----------	--------------------------------------	-------------

**WARRANTY:**

**NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

**NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Finisher - Windshield - Side - Renew	<b>76.43.39</b>	0.1	07	DYC500020

**NOTE: Normal Warranty policies and procedures apply.**

**SERVICE INSTRUCTION:**

1. Install the new A-pillar exterior finisher retaining clips (see TOPIx Workshop Manual, section 501-08).