

Service Action K225: Charge Air Cooler Duct Bolt Torque Relaxation

SERVICE BULLETIN

02-SEP-14 | No.: 6-236NAS | Section: GENERAL INFORMATION | Market: CAN / USA

DESCRIPTION

An issue has been identified on a limited number of 2013 model year Jaguar XF (X250) vehicles, fitted with the 2.0L GTDi engine only, where a 'Restricted Performance' message and a Malfunction Indicator Lamp (MIL) are displayed in the Instrument Cluster.

AFFECTED VEHICLES

The VIN range of affected vehicles is S51675-U00808.

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Retailers are required to **HOLD** all affected vehicles within your control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action.

Refer to Technical Bulletin K225NAS: *Charge Air Cooler Duct Bolt Torque Relaxation*, for detailed repair instructions.

PARTS

* **NOTE:** when ordering parts, order only the expected percentage demand of parts identified

DESCRIPTION	PART No. / SUNDRY CODE	QTY. / VALUE	EXPECTED % OF VEHICLES REQUIRING PARTS
Bolt/Washer	C2D4727	2	100
Bolt	C2D2734	2	100
Nut	C2P2765	4	100

TOOLS

Refer to Workshop Manual for any required tools

WARRANTY

NOTE: Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code '**K225**' along with the relevant Option Code. SRO and parts information is included for information only. The drive in / drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **31 July 2016** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS / SUNDRY CODE	QTY. / VALUE*
K225	D	Charge air cooler end tank - Rework	18.91.52	2.80	C2D4727	2
		Read and clear DTCs	86.99.78	0.20	C2D2734	2
					C2P2765	4
K225	E	Charge air cooler end tank - Rework	18.91.52	2.80	C2D4727	2
		Read and clear DTCs	86.99.78	0.20	C2D2734	2
					C2P2765	4
		Drive in/drive out	10.10.10	0.10	-	-

Normal Warranty policies and procedures apply