

# Technical Service Bulletin



## 17 Checking engine oil level with dipstick T40178, but adjustment values are not available in Elsa

17 14 50 2038129/1 August 15, 2014.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2008 - 2014	All	Not Applicable

## Condition

A check with the engine oil service dipstick T40178 is necessary, but the adjustment values for the dipstick are not available in the Elsa repair manual.

## Technical Background

Because of a system change, the adjustment values for the service dipstick T40178 were removed from the repair manual.

## Production Solution

The adjustment values will be added to the repair manual at the next update.

## Service

The adjustment values for the dipstick are included in the attached document.

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

## Required Parts and Tools

Service dipstick T40178

## Additional Information

All parts and service references provided in this TSB (2038129) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.