GPOP - Issue Review System

Part Number: 1TB32JW4A\$, 1TB32JXWA\$

Part Description: Clockspring/ Steering Column Module

Issue The steering angle sensor on Fiat 500 is serviced as part of the Electric Power **Description:** Steering (EPS) steering column not the Clockspring.~

Please refer to section 19 EPS steering column for service procedures.~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.