



NUMBER: 24-006-14

GROUP: Heating & Air
Conditioning

DATE: September 03, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

SUBJECT:

Poor AC Performance

OVERVIEW:

This bulletin involves inspecting the A/C condenser for leakage and replacing if required.

MODELS:

2014 (JS) Avenger/200

NOTE: This bulletin applies to vehicles built on or after November 18, 2013 (MDH 1118XX) and on or before January 1, 2014 (MDH 0101XX).

SYMPTOM/CONDITION:

The customer may experience poor A/C performance from the HVAC system due to refrigerant loss through the condenser.

DIAGNOSIS:

If the customer describes this symptom, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68004053AA	Condenser

REPAIR PROCEDURE:

NOTE: Be sure to review all warnings and cautions before proceeding, refer to the detailed information available in DealerCONNECT> TechCONNECT under: Service Info> 24 - Heating and Air Conditioning> Plumbing> Warning.

1. Inspect the entire condenser for signs of leaking refrigerant. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT> under: Service Info> 24 - Heating and Air Conditioning> Diagnosis and Testing> Diagnosis and Testing - Refrigerant System Leaks.
2. Was a condenser leak found?
 - a. Yes >>> Proceed to repair procedure [Step #3](#).
 - b. No >>> This bulletin does not apply, proceed with normal diagnostics.

3. If the condenser is found to be leaking refrigerant, replace the condenser. Refer to the detailed removal/installation procedures available in DealerCONNECT> TechCONNECT> under: Service Info> 24 - Heating and Air Conditioning> Condenser, A/C> Removal/Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
24-45-05-92	Condenser- Replace (2 - Skilled)	7 - A/C AND HEATING	1.7Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------