



NUMBER: 09-005-14

GROUP: Engine

DATE: September 05, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 14-071. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Replace Engine Drive Belt

OVERVIEW:

This bulletin involves replacing the engine serpentine belt.

MODELS:

2014- 2015

(KL)

Jeep Cherokee (International Markets Only)

NOTE: This bulletin applies to vehicles equipped with 2.0L I4 Turbo Diesel Engine (sales code EBT) built on or before July 02, 2014 (MDH0702).

SYMPTOM/CONDITION:

The engine drive belt may exhibit a noise.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
1	04627678AC	Auxiliary belt

REPAIR PROCEDURE:

1. Replace the engine drive belt. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info > 07 - Cooling > BELT, Serpentine > Removal/Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
07-20-17-92	Belt, Serpentine Replace (1 - Semi-Skilled)	10 - Diesel	0.3 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------