

Key cap fitting.pdf

| | |
|---------------|---|
| Reference | SSM71538 |
| Models | XK / X150 XJ / X351 XF / X250 |
| Title | Door Lock Cylinder Cover - Fitment at PDI / Replacement. |
| Category | Body |
| Last modified | 05-Feb-2014 00:00:00 |
| Symptom | 112000 Latches/Locks & Security |
| Content | <p>Issue: Customer may report door lock cylinder cover missing.</p> <p>Cause: Cylinder cover may have been incorrectly fitted at PDI or after emergency vehicle entry.</p> <p>Action: The sequence of installing is shown on the attached doc. Please make sure that the door lock cylinder cover is pushed firmly in the sequence shown to install all 3 clips. The cover will now be securely attached to the vehicle.</p> <p><u>Ensure correct fitment by testing with a vigorous pull</u></p> |