

<b>Reference</b>	SSM71538
<b>Models</b>	XK / X150 XJ / X351 XF / X250
<b>Title</b>	Revised - door lock cylinder cover, fitment at PDI / replacement
<b>Category</b>	Body
<b>Last modified</b>	04-Aug-2014 00:00:00
<b>Symptom</b>	112000 Latches/Locks & Security
<b>Attachments</b>	Bezel SSM Images (1).pdf, IMG_0976 (4).MOV
<b>Content</b>	<p><b>Issue:</b> Customer may report door lock cylinder cover missing.</p> <p><b>Cause:</b> Cylinder cover may have been incorrectly fitted at PDI or after emergency vehicle entry.</p> <p><b>Action:</b> The sequence of installing is shown on the attached doc. Please make sure that the door lock cylinder cover is pushed firmly into place so that an audible 'click' can be heard, following the sequence to install all 3 clips in the correct order 1-2-3. Ensure correct fitment by testing with a vigorous pull, the cover will now be securely attached to the vehicle as shown in the video attachment.</p> <p><b>NOTE: We are currently in the process of updating owner and PDI literature regarding this new revised procedure as current documentation may be incorrect.</b></p>