



**NOTIFICATION OF UPDATE PRIOR TO SALE
UPS8014-1b: SEAT BELT TENSIONER SYSTEM
CONNECTOR WIRING**

**SERVICE
BULLETIN**

28-OCT-14 | NO.: 6-250NAS | SECTION: GENERAL INFORMATION | MARKET: CAN / USA

DESCRIPTION

A potential issue has been identified on a number of 2014-2015 model year F-TYPE (X152) vehicles with the wiring connecting the Seat Belt Tensioner System to the main cabin harness. It is possible that the Seat Belt Tensioner System may not correctly indicate the presence of a child restraint or very light weight occupant.

AFFECTED VEHICLES

The VIN range of affected vehicles is K00074 - K19728.

ACTION TO BE TAKEN

Retailers are required to check DDW to ensure a vehicle is affected by Program Code 'K265' and **HOLD** only affected new vehicles in your control and withhold them from onward distribution and sale pending further notice.

SERVICE PROGRAM

Jaguar is currently in the process of developing a robust repair procedure. A further communication will be sent detailing the necessary action required for these vehicles.

Thank you for your cooperation in this matter. Jaguar Land Rover apologizes for any inconvenience this may cause.