

**NUMBER:** 23-027-14

GROUP: Body

DATE: October 01, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

#### THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 14-080. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

#### SUBJECT:

Zinc Coating Missing From Left Rear Close Out Panel

#### **OVERVIEW:**

This bulletin involves inspecting the Julian date on the left rear close out panel.

#### MODELS:

2015

(JK)

Wrangler

# NOTE: This bulletin applies to vehicles built on or after July 29, 2014 (MDH 0729XX) and on or before July 31, 2014 (MDH 0731XX).

#### SYMPTOM/CONDITION:

Zinc coating missing from left rear close out panel, no corrosion protection.

#### DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

#### **REPAIR PROCEDURE:**

- 1. On the left rear corner of the vehicle, behind the wheel, next to the frame, using a flash light, look in the hole identified in (Fig. 1).
- 2. Inspect the Julian date on the left rear close out panel (Fig. 1) and (Fig. 2).
- 3. Was the Julian date 205 ? (Fig. 2)
  - a. YES>>> Contact your Area Manager or Business Center Customer Relations/Warranty Manager for buy back instructions.
  - b. NO>>> This bulletin does not apply. Return vehicle to stock or customer.




Fig. 1 Left Rear Close Out Panel Inspection




Fig. 2 Julian Date

## POLICY:

Reimbursable within the provisions of the warranty.

## TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-85-84-90	Inspect The Julian Date On The Left Rear Close Out Panel (0 - Unskilled)	6 - Electrical and Body Systems	0.2 Hrs.

### FAILURE CODE:

ZZ Service Action	
-------------------	--