
Reference	SSM71995
Models	XK / X150
Title	XK Vehicles - Damaged Armrest Liner
Category	Body
Last modified	25-Sep-2014 00:00:00
Symptom	107000 Interior Trim
Attachments	Liner damage - PIC 1.pdf Removal process - PIC 2.pdf

ContentIssue:

Customers have reported that the Armrest liner is damaged – eg: Corner broken – See pic 1 as an example

Cause::

Poor initial fit / interference contact

Action:

If any damage is found on the armrest liner only, then replace the liner assembly, which is available as a separate part, having the service number XR8-49520

How to Repair

1. With armrest fully forward raise vertically
2. Hold armrest in position and pull liner firmly from centre to release clips – See pic 2 as an example
3. Fit replacement liner and ensure that all 3 clips engage