Reference	SSM66837
Models	LR2 / L359
Title	Gearshift Interlock Button / Spring Issue
Category	Driveline
Last modified	09-Jun-2014 00:00:00
Symptom	503000 Automatic Transmission Engagement Concerns
Attachments	1selector.pdf
Content	Issue:
	The gearshift interlock button inoperative or spring has come adrift (See Attached)
	Cause:
	The interlock button mechanism has been modified to prevent this issue from Vin No. H372254

Please only submit further EPQR's for any vehicles that are post the assured Vin of H372254