

<b>Reference</b>	SSM71864
<b>Models</b>	Range Rover / L405 Range Rover Sport / L494
<b>Title</b>	Rear camera faulty parts are being returned with rubber surround
<b>Category</b>	Electrical
<b>Last modified</b>	04-Jun-2014 00:00:00
<b>Symptom</b>	206000 Warning Indicators
<b>Attachments</b>	camara ssm.pdf
<b>Content</b>	<p><b><u>Issue</u></b> When returning failed parts through warranty it has been found that the rubber surround is still attached to the camera lens. This applies to both high line and low line rear camera.</p> <p><b><u>Action</u></b> Please ensure that if there is requirement to replace this part you remove the item highlighted in the attachment and fit it to the new lens before installation.</p>