



Service Bulletin

File in Section: -

Bulletin No.: PIT5283

Date: May, 2014

PRELIMINARY INFORMATION

Subject: Radio Touchscreen Inaccurate or Difficult To Use

Models: 2014 Buick LaCrosse, Regal
2013-2014 Cadillac ATS, SRX, XTS
2014 Cadillac CTS Sedan, ELR
2015 Cadillac Escalade
2014 Chevrolet Corvette, Impala
2014-2015 Chevrolet Silverado 1500
2015 Chevrolet Tahoe, Silverado HD, Suburban
2014-2015 GMC Sierra 1500
2015 GMC Sierra HD, Yukon Models
with RPOs IO5, IO6, or UY4

Condition/Concern

Customer may state that the touchscreen is inaccurate or that the display does not seem to respond with the desired operation when pressed.

Recommendation/Instructions

Perform a touch screen calibration and reevaluate the concern. The procedure is accomplished from the home screen by selecting settings>display>touchscreen calibration and following the onscreen prompts.

Warranty Information

For vehicles repaired under warranty, please refer to the latest version of bulletin 06-08-47-001 for warranty information on control module reset/configuration.