



# Service Bulletin

File in Section: -

Bulletin No.: PIT5302

Date: July, 2014

## PRELIMINARY INFORMATION

**Subject:** Turn Signal Indicator Does Not Match Audible Warnings (Click-Clack)

**Models:** 2010-2015 GMC Terrain  
2010-2015 Chevrolet Equinox

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Customer may have a concern where the turn signal indicators on the IPC do not match the audible warnings (Click-Clack) from the speaker

### Recommendation/Instructions

Do Not replace parts or update software in any control modules.

Inspect battery condition with the GR8 (EL-50313) and verify the charging system is operating correctly.

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4041512	Battery Charging and Testing	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.