



September 16, 2014

ATB 41506-52545 REV2(1409)

Steering Feels Heavy; EPS Indicator Comes On With DTC 32-09 or 61-04**(Replaced by 14-058, Warranty Extension: Electric Power Steering With DTC 32-09 or 61-04)**

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.