



Service Bulletin

File in Section: -

Bulletin No.: PI1092

Date: November, 2013

PRELIMINARY INFORMATION

Subject: Rough Idle Concern**Models:** 2013 Cadillac ATS
Equipped with 2.5L Engine (RPO LCV)**Condition/Concern**

Some customers may comment on a rough idle when the engine is at operating temperature. The roughness is felt primarily in the seat of the vehicle.

Recommendation/Instructions

Updated software calibrations have been released to address this condition. Reprogram the ECM (Engine Control Module) and the FPCM (Fuel Pump Control Module). This is NOT a sequential programming event. Each module must be programmed separately.

Contact Techline Customer Support Center (TCSC) at 1-800-828-6860 (English) or 1-800-503-3222 (French) for instructions to reprogram the ECM and FPCM with the special VCI number provided. Use Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the SPS procedures in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2880138*	Reprogram ECM and FPCM	0.5 hr
*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		