

<b>POLICE INTERCEPTOR SEDAN - AIR BAG WARNING LAMP - DRIVER SEAT BELT BUCKLE SENSOR DTCS B0050:11 OR B0050:13 AND/OR LOOSE/DAMAGED PLASTIC BUCKLE COVER</b>	<b>TSB 13-12-11</b>
---	---------------------

**FORD:**

2013 Taurus

This article supersedes TSB 13-5-25 to update the Service Procedure.

**ISSUE**

Some 2013 Taurus Police Interceptor sedan vehicles may exhibit an illuminated air bag warning lamp with driver seat belt buckle sensor diagnostic trouble codes (DTCs) B0050:11 or B0050:13 and/or a loose/damaged plastic buckle cover.

**ACTION**

Follow the Service Procedure Steps to correct the condition.

**SERVICE PROCEDURE**

Replace the left hand front safety belt buckle assembly. Refer to Workshop Manual, Section 501-20A for removal and installation.

PART NUMBER	PART NAME
DG1Z-5461203-BA	Seat Belt Buckle

OPERATION	DESCRIPTION	TIME
131211A	2013 Taurus Police Interceptor Sedan: Check DTCs And Replace The Left Front Safety Belt Buckle Includes Time To Clear Codes.	0.8 Hr.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage  
 Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
5461203	28

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.