

**View Message****Sent on** 01 29 2014 **Expires on** 02 11 2014**From** Parts and Service Division**Subject** Request for Parts: 2004-2008 TL & TSX MIL On with DTC P2138

**To:** All Acura Service Managers/Consultants  
**From:** Technical Research & Support Group  
**RE:** Request for Parts: 2004-2008 TL & TSX MIL On with DTC P2138

**This message is solely directed to Acura dealership personnel; please handle accordingly.  
Print this iV message and provide a copy to the Shop Foreman and all Service Consultants.**

**Background**

American Honda (AHM) is investigating certain 2004-2008 TLs & TSXs with a complaint of the Malfunction Indicator Lamp (MIL) on with the DTC P2138 (Accelerator Pedal Position Sensor A/B Incorrect Voltage Correlation) stored and poor engine performance. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting any further repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. MIL On with DTC P2138 stored
2. APP (Accelerator Pedal Position) sensors have not been replaced previously
3. Mileage must be over 80,000 miles

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.