

ONLINE AUTOMOTIVE SERVICE INFORMATION
FOR MARCH 2014

SB-10055323-2876

44459 2014 Fusion - 1.5L GTDI - Extended Crank And/Or Run Rough After Engine Start -
MIL With P00C6

Some 2014 Fusions equipped with a 1.5L Gasoline Turbocharged Direct Injected (GTDI) engine may exhibit extended engine cranking time and/or a run rough condition after engine start-up with a Malfunction Indicator Lamp (MIL) illuminated and a Diagnostic Trouble Code (DTC) P00C6. Follow pinpoint test HP in the online PCED for DTC P00C6, which has been revised to assist with proper diagnosis.