

SB-10055325-1605

ONLINE AUTOMOTIVE SERVICE INFORMATION FOR MARCH 2014

44439 2013-2014 Police Sedan and Utility headlamp terminal overheating

2013-2014 Police Utility and Sedan OE headlamp bulbs are designed to meet certain wattage, bulb life, and photometric requirements. If headlamp bulb replacement is required, Ford recommends the Phillips HIR2 LL for the Sedan and Sylvania 9005 HL+ for the Utility. Other headlamps may have different wattage and bulb material specifications that may cause premature bulb failure and/or overheated connector terminals.
