

## **SB-1005576-1686**

### **ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR FEBRUARY 2014**

44414 Some 2011-2014 F-Super Duty Vehicles - Body Cab Leans To One Side - Service Tip

Some 2011-2014 F-Super Duty vehicles may exhibit a customer complaint of front Body Cab lean to one side. This optical difference may be normal body architecture of vehicle and may be affected by vehicle loading. If a customer complaint of front lean is identified, refer to updated diagnostic and repair detail in Professional Technician Society (PTS) workshop manual section (WSM) 204-00. Note: Failure to use the updated diagnostics may lead to incorrect repairs. Ensure no aftermarket components or equipment are affecting the vehicle's Body/Suspension prior to evaluation or repair. If aftermarket components are found, the vehicle's body/chassis must be returned to original specifications before accurate evaluation and diagnosis is performed.