Reference SSM71438

LR4 / L319

Models Range Rover / L322

Range Rover Sport / L320

Title oil leak from transfer case output flange - 2008 to 2010

Model Year

Category Driveline

Last modified 24-Jan-2014 00:00:00

Symptom 508000 Transfer Case Concerns

Issue: Oil leak from transfer case output flange

Cause: The cause is under investigation

Action: Engineering is investigating oil leaks from the transfer case output flange on the following vehicles only: 2008 to 2010 Model Years - Discovery 4 (LR4), Range

Rover, and Range Rover Sport.

Although this issue can be repaired, the engineers would like to get a small number of transfer cases returned to Content the supplier so the cause of the leak can be fully investigated.

Where the customer will not be troubled, please report this issue using an EPQR. Pictures of the issue should be included. The information will be reviewed by the engineer, who will make a decision if the transfer case assembly should be replaced or if the flange should be repaired. A Priority Return Request will be raised where required.