

[Next Unread Message](#)**View Message**

Sent on 06 12 2014 **Expires on** 06 26 2014
From Parts and Service Division
Subject Request for Visit: 2014 Accord V6 Rear Cylinder Head Cover Gasket Leak

To: All Honda Service Managers/Advisors
From: Technical Research & Support Group
RE: Request for Visit: 2014 Accord V6 Rear Cylinder Head Cover Gasket Leak

**This message is solely directed to Honda dealership personnel; please handle accordingly.
Print this iN message and provide a copy to the Shop Foreman and all Service Advisors.**

Background

American Honda (AHM) is investigating certain 2014 Accord V6s with a complaint of oil leak at the rear cylinder head cover gasket. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to your attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. V6 model only.
2. Vehicle must be under the New Vehicle Limited Warranty (3 year/36,000 miles).
3. No extended warranty.
4. Leak must be from the V6 rear head cover gasket.
5. No previous removal of rear cylinder head cover.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.