

SB-10056003-1267**FORD:**

2007-2010 Edge

LINCOLN:

2007-2010 MKX

This article supersedes TSB 12-8-10 to update the Title, Issue Statement and Service Procedure.

ISSUE

Some 2007-2010 Edge and MKX vehicles may exhibit a customer concern of a growl or howl type-noise coming from the left or right rear wheel area.

ACTION

Follow the Service Procedure step to correct the condition.

SERVICE PROCEDURE

Replace the suspect rear wheel hub and bearing assembly with a new service part. Refer to Workshop Manual (WSM), Section 204-02.

PART NUMBER	PART NAME
7T4Z-1104-B	Hub Assy - FWD (2007-2008)
7T4Z-1104-C	Hub Assy - 4WD
9T4Z-1104-A	Hub Assy - FWD (2009-2010)
W712435-S439	Wheel Hub Nut - 4WD Inner & Outer (2 Req)
W520215-S440	Nut - Toe Link & Lower Arm Outboard (2 Req)
W500766-S439	Bolt - Toe Link & Lower Arm Outboard (2 Req)
W712459-S439	Bolt - Shock Absorber Lower Flag
W520214-S440	Nut - Shock Absorber Lower
W520414-S441	Nut - Stabilizer Bar Link
W712754-S439	Wheel Hub Bolt (4 Req)

OPERATION	DESCRIPTION	TIME
140098A	2007-2010 Edge/MKX FWD: Replace One (1) Rear Wheel Hub And Bearing (Do Not Use With Any Other Labor Operations)	0.6 Hr.
140098A	2007-2010 Edge/MKX AWD: Replace One (1) Rear Wheel Hub And Bearing (Do Not Use With Any Other Labor Operations)	1.2 Hrs.
140098B	2007-2010 Edge/MKX FWD: Replace Both (2) Rear Wheel Hub And Bearings (Do Not Use With Any Other Labor Operations)	1.0 Hr.
140098B	2007-2010 Edge/MKX AWD: Replace Both (2) Rear Wheel Hub And Bearings (Do Not Use With Any Other Labor Operations)	2.2 Hrs.

WARRANTY STATUS:

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

DEALER CODING

BASIC PART NO.	CONDITION CODE
1104	d4