

Service Campaign Bulletin



Mercedes-Benz

Campaign No 2014060002, June 2014

SB-10056070-9286

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 222 AMG (S-Class), Model Year 2014**
Update Transmission and Engine Control Module Software

This Service Campaign has been initiated because Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has determined that an update to the transmission and engine control module software will optimize the shift quality during coast down shifting. An authorized Mercedes-Benz dealer will update the transmission and engine control module software at the next workshop visit.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 996 vehicles are affected.

Order No. P-SC-2014060002

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin


Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Procedure

Note:

- Use DAS/Xentry 05-06/14 with all associated patches or higher.
 - Follow the steps exactly as described in DAS/Xentry.
 - Connect battery charger (battery voltage  >12.5V).
 - Ensure all electrical consumers are switched-off.
 - In the event of software/SCN update issues, contact Star Diagnosis User Help Desk. Please refer to the "pre-call" check list before contacting UHD
 - Refer to Star Diagnosis System (SDS) Best Practices Guide.
1. Install transmission control unit software:
 - Quick test view / VGS Fully integrated transmission control / Adaptations / Control unit programming
 - Follow on-screen instructions.
 2. Install engine control unit software:
 - Quick test view / ME Motor electronics / Adaptations / Control unit programming.
 - Follow on-screen instructions.

Note:

Please verify ME and transmission software number change after performing the software update.

Warranty Information

Operation: Connect/disconnect battery charger (02-5058)
 Star Diagnosis System (SDS), Connect/disconnect (02-4762)
 Update fully integrated transmission control module software (02-8549)
 Update engine control module software (02-8550)

Damage Code	Operation Number	Labor Time (hrs.)
54 982 43 8	02-5058	0.1
	02-4762	0.1
	02-8549	0.1
	02-8550	0.1

Note

Operation Number labor times are subject to change.