

SB-10056071-5357



Reliability Driven™

Service Bulletin No. 3082

<small>MODEL</small> D / J4500 Series	<small>TYPE</small> Service Information	<small>SECTION/GROUP</small> 8-Engine	<small>DATE</small> Mar 27, 2014
<small>SUBJECT</small> CUMMINS ISX ENGINE 2311 FAULT CODE			
<small>CONDITIONS</small> Service Information Only			

Description:

Cummins Inc. has notified Motor Coach Industries (MCI) that customers operating a coach equipped with a Cummins ISX engine that has experienced an active 2311 fault code are instructed to contact the Cummins Service Network.

Cummins is installing a new ECM calibration that will correct the logged code.

NOTICE

This program is being performed only by Cummins Service Network and its authorized dealers. Therefore all parts and labor required for this program, on MCI coaches with an engine under warranty, will be provided by Cummins.