



**SB-10056237-3582**

File in Section: -

Bulletin No.: PI1235

Date: May, 2014

# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Loose Ground Terminal Repair and Proper Labor Code

**Models:** 2012-2014 GM Passenger Cars and Trucks

### **Condition/Concern**

Some customers may comment on one or more of the following:

- DIC messages
- SES Light ON
- IPC warning indicators
- Accessories malfunctioning.

This may be caused by loose ground terminal connections.

### **Recommendation/Instructions**

Technicians should inspect the wire/terminals for damage. If no damage is found, tighten the ground nut to proper torque and use labor code 5430962 — Ground Connection Repair . Do not replace a wire or ground terminal if damage is not present when reattaching the connection with the proper torque would complete the repair. Refer to Fastener Tightening Specifications in SI.