

SB-10056248-1733

Reference	SSM66837
Models	LR2 / L359
Title	Gearshift Interlock Button / Spring Issue
Category	Driveline
Last modified	09-Jun-2014 00:00:00
Symptom	503000 Automatic Transmission Engagement Concerns
Attachments	1selector.pdf

Content**Issue:**

The gearshift interlock button inoperative or spring has come adrift (See Attached)

Cause:

The interlock button mechanism has been modified to prevent this issue from Vin No. H372254

Action:

Please only submit further EPQR's for any vehicles that are post the assured Vin of H372254

