



Service Bulletin

File in Section: -

Bulletin No.: PIT5306

Date: August, 2014

PRELIMINARY INFORMATION

Subject: TAC Part Restriction – Instrument Panel Cluster (IPC)

Models: 2014 Chevrolet Silverado 1500
2015 Chevrolet Silverado, Suburban, Tahoe
2014 GMC Sierra 1500
2015 GMC Sierra, Yukon models

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

US Dealers - Effective July 30, 2014 the IPC for these vehicles will be placed on restriction through the General Motors Technical Assistance Center. Please review recommendations below PRIOR to contacting TAC.

Canada Dealers - This PI is for US DEALERS ONLY, please contact York Electronics directly at (888)650- 9675 (Oshawa) or (800)361-2894 (Calgary).

Recommendation/Instructions

If the IPC locked up during a SPS Programming event, please reference the latest version of PI1212 and complete all steps PRIOR to contacting TAC.

Important: As noted in that PI, if the IPC programming still cannot be completed after completing the recommended steps, please contact the Techline Customer Support Center (TCSC) at 1-800-828-6860.

If vehicle came in with an IPC concern (example: gauges inop or IPC display malfunctions) and normal diagnostics lead to IPC replacement contact TAC so IPC replacement can be authorized. TAC U.S. can be reached at 1-877-446-8227.

Important: When calling TAC, be certain to select the Electrical prompt and be prepared to provide the IPC Part Number that is currently in the vehicle.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.