

SB-10056408-5329



Update Prior to Sale UPS3114: Trailer Harness CJB Connector Pin Locations

SERVICE BULLETIN

16-APR-14 | No.: SGI14-14 | Section: GENERAL
INFORMATION | Market: CAN / USA

DESCRIPTION

An issue has been identified on a limited number of 2014 model year Land Rover LR4 vehicles within the listed VIN ranges where the Central Junction Box (CJB) connector has incorrect pin assignments. The connector has pin location '1' wired in error where pin location '44' should be wired. If a trailer wiring harness is installed, the trailer's side and outer marker lamps do not illuminate.

AFFECTED VEHICLES / OWNER NOTIFICATION

The VIN range of affected vehicles is:

- LR4 (L319) EA699718-EA713882

ACTION TO BE TAKEN

Retailers must use DDW system vehicle inquiry screen to check for all affected vehicles within the VIN range that are in their control for 'Q384' eligibility and refrain from releasing these vehicles for new or used vehicle sale until further instructions are provided.

SERVICE PROGRAM

Land Rover is currently in the process of developing a robust repair procedure. A further communication will be sent detailing the necessary action required for vehicles in retailer inventory.

Thank you for your cooperation in this matter. Land Rover apologizes for any inconvenience this may cause.