SB-10056424-5068

Reference SSM71780

Models Range Rover (All New) / L405

Title Vehicle jack did not operate correctly during use.

Category Chassis

Last modified 06-Mar-2014 00:00:00

Symptom 307000 Jack/Tool & Spare

Issue:

A customer reports the jack did not operate correctly when raising the vehicle.

Cause:

JLR engineering are currently investigating to understand any situations where the jack does not function as intended.

Action:

Where possible raise an ePQR answering as best as possible the questions detailed below:

1. Were people in the vehicle whilst using the jack, if yes, how many?

Content 2. Which Tyre required changing?

- 3. Which wheel was the chock applied to?
- 4. What was the road surface the vehicle was jacked up upon?
- 5. Was the road flat or on a hill?
- 6. Is the vehicle fitted with side steps? If yes, fixed or deployable?
- 7. Did the customer have any specific issues whilst using the jack?
- 8. Was the ground wet/dry/icy?
- What suspension height was the vehicle set to? (Access/Normal/Off Road)
- 10. What position was the transmission in?