

SB-10056436-5045

Reference	SSM71947
Models	LR4 / L319 LR2 / L359 Range Rover Sport / L320
Title	Steering Gear Input Shaft Seal Leakage
Category	Chassis
Last modified	15-Aug-2014 00:00:00
Symptom	303000 Steering/Handling
Attachments	Input Shaft Seal and Pinion Seal.pdf
Content	<p><u>Issue:</u> When investigating a customer reported steering issue it is found that there is oil/fluid present around the steering gear input shaft.</p> <p><u>Cause:</u> Oil or Grease Leak past input shaft seal through normal use OR seal failure.</p> <p><u>Action:</u> If an input shaft seal is suspected of leaking please refer to the attached images to understand what level of grease / oil leakage is from normal operation of the steering system.</p>