

SB-10056478-7840**Noise from engine compartment**

Topic number	LI43.05-P-058344
Version	2
Design group	43.05 Vacuum pump
Date	07-29-2014
Validity	G 500 as of code XZ2
Reason for change	Model designation assignment corrected
Reason for block	

Complaint:

Constant noise from the engine compartment.

Cause:

Interlock switch vacuum pump runs constantly, check valve missing.

Remedy:

Install check valve.

Attachments	
File	Description
Durchflussrichtung.jpg	Valve flow direction
Verbauort.jpg	Installation location

Symptoms

Chassis/suspension / Brake system / Service brake / Brakes, Vacuum System / Vacuum pump leaky/noises

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other ma- ke part
A 002 140 84 60			Valve	1	Flow direction to pump.	X	

Work units

Op. no.	Operation text	Time	Damage code	Note
		3 AW	43051 36	

Validity		
Vehicle	Engine	Transmission
G (463)	273	*

Full model designation breakdown		
Vehicle	Engine	Transmission
463.202	273.963	722.904
463.202	273.969	722.904
463.222	273.963	722.904
463.222	273.969	722.904
463.236	273.963	722.904
463.236	273.969	722.904
463.237	273.963	722.904
463.237	273.969	722.904
463.242	273.963	722.904