



**SB-10056482-1135**

---

**SERVICE BULLETIN**

---

Classification: RS14-014	Reference: NTB14-096	Date: October 13, 2014
-----------------------------	-------------------------	---------------------------

**2015 FRONTIER, XTERRA AND ARMADA; DIAGNOSIS AND REPAIR PROCEDURE FOR B00A0 DTC'S**

**APPLIED VEHICLES:** 2015 Frontier (D40)  
2015 Xterra (N50)  
2015 Armada (TA60)

**SERVICE INFORMATION**

If DTC **B00A0** (OCCUPANT CLASSIFICATION SYSTEM CONTROL UNIT) is set as current in the Air Bag Diagnosis Sensor Unit:

- Follow the "DTC/CIRCUIT DIAGNOSIS" procedure for DTC B1017-B1022 (OCCUPANT SENS C/U) to repair the vehicle.

Refer to the Electronic Service Manual (ESM) section **SRC – SRS Airbag Control System** for procedure.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.