



Technical Journal

TITLE:

Gearshift service required

REF NO: TJ 29426	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada		
PARTNER: 3 US 7510 Volvo Cars North America		ISSUE DATE:		
FUNC GROUP: 4322	FUNC DESC: Gear lever carrier, parts	YEAR 2014	MONTH 09	DAY 26
Page 1 of 2				

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
1XX					0		2013-2013		-	201220-201319
1XX					6		2013-2013		-	201220-201319
275					0		2013-2013		-	201220-201319
275					6		2013-2013		-	201220-201319

CSC Customer Symptom Codes

Code	Description
IV	Text window and warning symbol/Text message

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
TCM	P093112	Intermittent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DIM = Driver Information Module

GSM = Gear Selector Module

**DESCRIPTION:**

Message in "DIM" gearshift service required might be shown. This together with DTC mentioned above. This is most likely due to a SW problem in GSM.

PRODUCT MODIFICATION:

N/A only valid for MY2013

VEHICLE REPORT:

If the vehicle exhibits the condition listed in this TJ but is either, not fixed by replacing the GSM or is outside of the structure week range above, then submit a Vehicle Report.

SERVICE:

Replace GSM P/N 31437116.