

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR AUGUST 2014

SB-10056750-7531

44664

2008-2010 - F-Super Duty - 6.4L - Exhaust Odor - Exhaust Manifold Leak Service Tip

Some 2008-2010 F-Super Duty vehicles equipped with a 6.4L diesel engine may exhibit an exhaust leak from an exhaust manifold. These leaks may be caused by a warped exhaust manifold. When repairing exhaust manifold leaks on a 6.4L diesel engine, be sure to use the Exhaust Manifold Cleaning and Inspection procedure that is in the WSM (Workshop Manual) section 303-00 Engine System | General Information. This procedure provides the specification and the proper method for checking the exhaust manifold sealing surface for warpage.