



Service Bulletin

File in Section: -

Bulletin No.: PIC6052

Date: December, 2014

PRELIMINARY INFORMATION

Subject: False Blind Side Alert

Models: 2014 Buick LaCrosse
2014 Chevrolet Malibu
Equipped with Obstacle Detection Side Active Safety (RPO UKC or UFT)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Blind side alert may become active with no objects within range of sensors.

If this occurs no DTC will be stored.

Recommendation/Instructions

Inspect rear bumper fascia for signs of damage. If no fascia damage is found, reprogram the B2181L Side Object Sensor Module. Refer to B2181L Side Object Sensor Module Programming and Setup in SI.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810765	Side Object Sensor Reprogramming with SPS	0.3 hr

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.