

UPDATE PRIOR TO SALE UPS6014-2b: BRAKE BOOSTER SOLENOID CONNECTOR SPRING LOCKING MECHANISM NOT ENGAGED

SERVICE BULLETIN

13-NOV-14 NO.: 6-253NAS SECTION: GENERAL MARKET: CAN / USA

INFORMATION

DESCRIPTION

A potential issue has been identified on a limited number of 2014-2015 model year XJ (X351) vehicles where the brake booster solenoid connector spring locking mechanism may not be engaged and as a result there may be a loss of the ECO Stop/Start function.

AFFECTED VEHICLES

The VIN range of affected vehicles is V73092-V75959.

See the attached list of specific affected VINs.

ACTION TO BE TAKEN

Retailers are required to check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action. Retailers are required to HOLD only affected vehicles in the above VIN range that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin UPS6014-2bNAS, *Update Prior to Sale: Brake Booster Solenoid Connector Spring Locking Mechanism Not Engaged*, for detailed repair instructions.

PARTS

No parts required

TOOLS

Refer to Workshop Manual / Service Instruction for any required tools

WARRANTY

NOTE: Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code 'K253' together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **15 March 2015** closure date must be submitted for payment within 30 calendar days of completion of the repair.

Program Code	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NO. / SUNDRY CODE	QTY. / VALUE
K253	В	Check and if required connect the brake booster solenoid electrical connector	76.10.01	0.30	-	-
K253	С	Check and if required connect the brake booster solenoid electrical connector Drive in/drive out		0.30 0.10	-	-

Normal Warranty policies and procedures apply

UPS6014-2B: AFFECTED VIN LIST

CANADA

VIN	RETAILER No. / NAME	VIN	RETAILER No. / NAME
V73297	3204 Decarie Motors	V73868	4389 Budds' Imported Cars
V73524	3204 Decarie Motors	V74145	4495 Coventry North Jaguar
V73092	3306 Jaguar Brossard	V74045	4503 Jaguar Laval
V75612	3306 Jaguar Brossard	V73479	4506 Jaguar Edmonton
V75839	4201 Jaguar Toronto	V75708	6058 Jaguar of Calgary

USA

USA			
VIN	RETAILER No. / NAME	VIN	RETAILER No. / NAME
V75556	0349 Byers Imports	V74857	5671 Ken Garff Jaguar
V74288	0617 Jaguar Minneapolis	V75274	5672 Autobahn Motorcars
V74285	0696 Alpine Jaguar	V73792	5696 Union Park Jaguar
V74769	0696 Alpine Jaguar	V74269	5701 West-Herr Jaguar
V75440	3937 Jaguar Allentown	V74336	5703 Galpin Jaguar
V75759	3937 Jaguar Allentown	V74763	5703 Galpin Jaguar
V75381	5299 Jaguar Rochester	V75561	5725 Manhattan Jaguar/NYC
V73152	5311 Jaguar Monmouth	V73354	5725 Manhattan Jaguar/NYC
V73741	5320 Jaguar Palm Beach	V73548	5725 Manhattan Jaguar/NYC
V73695	5320 Jaguar Palm Beach	V73813	5725 Manhattan Jaguar/NYC
V74005	5322 Jaguar Birmingham	V74310	5725 Manhattan Jaguar/NYC
V75276	5447 Jaguar Houston Central	V74022	5748 Jaguar Peoria
V74788	5536 Jaguar Naples	V74481	5748 Jaguar Peoria
V73347	5598 Jaguar Norwood	V75017	5756 Imperial Motors Jaguar of Lake Bluff
V74890	5601 Jaguar Chantilly	V75959	5759 Bobby Rahal Jaguar
V74561	5605 Jaguar West Chester	V73325	5767 Jaguar Naperville
V75916	5605 Jaguar West Chester	V73595	5768 Jaguar of Tampa
V75695	5612 Jaguar Huntsville	V74523	5777 Hennessy Jaguar Gwinnett
V75334	5618 Hennessy Jaguar	V74826	5777 Hennessy Jaguar Gwinnett
V75208	5625 Scott Jaguar	V74798	5786 Jaguar North Scottsdale
V75918	5631 Jaguar Indianapolis	V74808	5796 Jaguar Des Moines
V73530	5653 Cole European		