



ABOVE & BEYOND

UPDATE PRIOR TO SALE UPS9114-2B: ACCELERATOR
PEDAL DEFECTIVE SWITCH

SERVICE
BULLETIN

23-DEC-14

NO.: SGI14-52

SECTION: GENERAL
INFORMATION

MARKET: CAN / USA

THIS BULLETIN UPDATES AND SUPERSEDES SGI14-51

DESCRIPTION

A potential issue has been identified on a small number of 2015 model year Range Rover Sport (L494) and Range Rover (L405) vehicles where the accelerator pedal switch printed circuit board may not have been correctly soldered, leading to an intermittent connection. This may result in the vehicle entering restricted performance mode.

AFFECTED VEHICLES

Certain vehicles within the following VIN ranges are affected:

- Range Rover Sport (L494) FA504511-FA510214; FA601763-FA604514
- Range Rover (L405) FA197042-FA203357

ACTION TO BE TAKEN

Retailers are required to **HOLD** only affected vehicles that are within your control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the any necessary rework action. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin Q442 UPS9114-2bNAS1, *Accelerator Pedal Defective Switch*, for detailed repair instructions.

PARTS

★ - order only AFTER confirming the need for replacement as detailed in Technical Bulletin Q442 UPS9114-2bNAS. Refer to SSM72100 for correct accelerator pedal part number per affected serial number.

DESCRIPTION	PART NO. / SUNDRY CODE	QTY. / VALUE	EXPECTED % OF VEHICLES REQUIRING PARTS★
Accelerator pedal – standard	LR062129	1	★ order only AFTER confirming the need for replacement as detailed in Technical Bulletin Q442 UPS9114-2bNAS
Accelerator pedal – unique metal finish	LR072171	1	★ order only AFTER confirming the need for replacement as detailed in Technical Bulletin Q442 UPS9114-2bNAS

TOOLS

Refer to Service Instruction / Repair Procedure for any required tools

WARRANTY

NOTE: [check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action.](#)

At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **06 June 2015** closure date must be submitted quoting Program Code '**Q442**' together with the relevant Option Code from the table. The SRO and part information listed have been included for information only. The Option Code(s) that allows for the drive in / drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

Warranty claims must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART No. / SUNDRY CODE	QTY. / VALUE
Q442	A	Check the accelerator pedal serial number - no further action	05.10.10	0.10	-	-
Q442	K	Check the accelerator pedal serial number - no further action	05.10.10	0.10	-	-
		Drive in/drive out	02.02.02	0.20	-	-
Q442	B	Check and replace accelerator pedal	19.20.01	0.20 - Range Rover Sport (L494) 0.10 - Range Rover (L405)	LR062129	1
Q442	C	Check and replace accelerator pedal	19.20.01	0.20 - Range Rover Sport (L494) 0.10 - Range Rover (L405)	LR062129	1
		Drive in/drive out	02.02.02	0.20	-	-
Q442	D	Check and replace accelerator pedal	19.20.01	0.20 - Range Rover Sport (L494) 0.10 - Range Rover (L405)	LR072171	1
Q442	E	Check and replace accelerator pedal	19.20.01	0.20 - Range Rover Sport (L494) 0.10 - Range Rover (L405)	LR072171	1
		Drive in/drive out	02.02.02	0.20	-	-

Normal Warranty policies and procedures apply