

SB-10057628-1875

Reference	SSM71963
Models	F-TYPE / X152
Title	Front to rear power cable detachment from the through panel stud
Category	Electrical
Last modified	05-Sep-2014 00:00:00
Symptom	203000 Basic Electrical
Attachments	Doc11.pdf
Content	<p><u>Issue:</u> The front to rear power cable has become detached from the through panel stud, where it passes through the boot floor.</p> <p><u>Cause:</u> Failure of the friction weld between the cable and stud. (see file attached as an example).</p> <p><u>Action:</u> In order to effect a first time repair it will be necessary to replace the whole front to rear power cable assembly. There is no temporary repair or lower level assembly that is currently available.</p>