

SB-10057629-1648

Reference	SSM71991
Models	Range Rover Evoque / L538
Title	L538 Front wiper inoperative
Category	Body
Last modified	30-Sep-2014 00:00:00
Symptom	102000 Window/Glass
Attachments	

Content

Issue: When front windscreen wipers are operated (any speed selected) there is no response. AND/OR during windscreen operation the wipers sieze mid-cycle and remain unresponsive. ALSO windscreen wipers un-responsive when in certain wiper speed selections i.e. No. 2.

Cause: Under Engineering investigation

Action: ALL markets please raise EPQRs for issues. UK dealers raise EPQR and contact J Buxton (jbuxton@jaguarlandrover.com) 07823525655 or J Pope (jpoppe5@jaguarlandrover.com) 01514483260.