

ONLINE AUTOMOTIVE SERVICE INFORMATION
FOR JULY 2014

SB-10057731-7761

44641 2013-14 C-MAX Energi and Fusion Energi - Fuel Door Sticking Closed

The fuel filler door on some 2013-14 C-MAX Energi and Fusion Energi vehicles may appear to stick closed or exhibit a delayed opening period. After pressing the fuel door release button on the center console, a delay of up to 15 seconds may be experienced before the fuel filler door latch is released and the door opens. This is normal system operation and no repairs should be attempted. Refer to the 'Fuel And Refueling' section of the owner guide for additional details.