

## **SB-10057735-3208**

### **ONLINE AUTOMOTIVE SERVICE INFORMATION FOR JULY 2014**

44651 2011 - 2014 F150 Rear View Camera Inoperative

Some 2011 - 2014 F150 equipped with a rear camera may have an inoperative rear camera due to improper reconnection of connector C4000 after a tailgate service repair or Spray-in Bedliner installation. Before beginning normal diagnosis check to see if the tailgate was recently removed for a service repair or a spray-in bedliner installation. If the tailgate was recently removed check connector C4000 to verify it was properly reconnected before starting normal diagnosis.