

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM  
FOR SEPTEMBER 2014

**SB-10057861-8466**

44732 2014-2015 Focus and Fiesta Equipped With DPS6 Transmission - Dual Clutch Friction Material Requires 1000 Mile (1600K) Break-In Before Servicing

2014-2015 Focus and Fiesta Vehicles equipped with the DPS6 Transmission that have not completed the 1000 miles (1600K) required to properly break in the dual clutch friction material should not have the clutch assembly replaced for symptoms of light shudder unless a fluid leak has been verified. Engineering recommends performing the IDS Service Routine Transmission Adaptive Learning to reset the clutch travel please follow the procedure located in the Work Shop Manual (WSM) 307-01.