

SB-10057862-4331

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR SEPTEMBER 2014

44719 2010-2014 Mustang - Driver Or Passenger Power Seat Binding - Grinding Or Clicking
Noise During Power Seat Operation

Some 2010-2014 Mustang vehicles may exhibit a power seat binding during seat control tilt and or lift adjustment operation. There may also be clicking or grinding noise heard from the seat track area, specifically coming from either the front tilt or rear vertical lift gearboxes. Service inventories have been updated with revised seat motor service kits(78617D66), for lower service part replacement procedure. Follow the On-line Workshop Manual (WSM) section 501-10 for diagnosis and replacement procedures. Use available service labor operations.