

SB-10057864-9528

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR SEPTEMBER 2014

44715 2013-2015 F-Super Duty 4x4-Intermittent or Inoperative Front Hubs

Some 2013-2015 F-Super Duty 4x4 vehicles may exhibit a condition of 4x4 not engaging, or 4x4 not staying engaged or unlocking. This may be the result of a loss of vacuum between the front hub lock assembly and the front axle shaft seal assembly due to concerns with the front axle hub seal(s). Workshop Manual Section 308-07A Pinpoint Test K has been updated to aid in correct diagnosis and repair. If a leak is confirmed in this location, please replace the axle shaft seal (3254). Use available Service Labor times.