

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR SEPTEMBER 2014

SB-10058064-1177

44708 2015 F650/750 SYNC Operation in Accessory Mode

Some 2015 F650/750 Medium Duty vehicles equipped with SYNC may exhibit a customer concern of the radio not operating with the ignition switch in Accessory position. This is a normal characteristic of the Audio System when equipped with SYNC and no repairs should be attempted. Refer to the Owner Manual section for Starting and Stopping the Engine - Ignition Switch for more information regarding operation of the audio system with the ignition switch in the Accessory position. Vehicles equipped with a non-SYNC radio will have functionality in the Accessory position of the ignition switch.